

03500.017693

PATENT

of Correction

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

in re Patent or:	Examiner: Sandra L. Brase
Akiyoshi YOKOI	Group Art Unit: 2852 U.S. Patent No.: US 6,941,092 B2 Issued: September 6, 2005 May 11, 2006
Appl. No.: 10/697,323	
Filed: October 31, 2003	
For: REMANUFACTURING METHOD FOR PROCESS CARTRIDGE	
	Certificate
	MAY 1 5 2006

Commissioner for Patents P.O. Box 1450 Alexandria, VA 22313-1450

CERTIFICATE OF CORRECTION UNDER RULE 322

Sir:

It is respectfully requested that a Certificate of Correction be issued by the Patent and Trademark Office due to errors which appear in the printed patent as a result of Patent and Trademark Office mistakes. A Certificate of Correction form (Form PTO-1050), in duplicate, is enclosed.

Although no fees are believed to be necessary, any fees deemed necessitated by this paper may be charged to Deposit Account No. 06-1205. A duplicate copy of this paper is enclosed.

Patentee's undersigned attorney may be reached in our Washington, D.C. office by telephone at (202) 530-1010. All correspondence should continue to be directed to our address given below.

Respectfully submitted,

Gary M. Jacobs

Attorney for Patentee Registration No. 28,861

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza
New York, New York 10112-3800
Facsimile: (212) 218-2200
GMI/IW

DC_MAIN 221926v1

- 2 -

PRINTER'S TRIM LINE

UNITED STATES PATENT AND TRADEMARK OFFICE

CERTIFICATE OF CORRECTION

PATENT NO.

US 6,941,092 B2

DATED

September 6, 2005

INVENTOR(S) :

Akiyoshi YOKOI

Page 1 of 1

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 14

Line 4, "developer" should read --developer; (New Paragraph) a first coupling frame (side cover 22) for coupling one end side of the photosensitive member unit 21 and one end side of the developing unit 20 to each other; and--.

Line 5, "or" should read -- for --.


MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza
New York, New York 10112-3800
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

Form PTO 1050 (Rev. 3-82) (Form#30) GMJ/Iw 221927v1

PATENT NO. 6,941,092 B2

No. of add'l. copies @ 30¢ per page



Stable Here Ould! PRINTER'S TRIM LINE

UNITED STATES PATENT AND TRADEMARK OFFICE

CERTIFICATE OF CORRECTION

PATENT NO.

US 6,941,092 B2

DATED

September 6, 2005

INVENTOR(S) :

Akiyoshi YOKOI

Page 1 of 1

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 14

Line 4, "developer" should read --developer; (New Paragraph) a first coupling frame (side cover 22) for coupling one end side of the photosensitive member unit 21 and one end side of the developing unit 20 to each other; and--.

Line 5, "or" should read --for--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza
New York, New York 10112-3800

(212) 218-2100 - Telephone

(212) 218-2200 - Facsimile

Form PTO 1050 (Rev. 3-82)

(Form#30) GMJ/Iw 221927v1

PATENT NO. 6,941,092 B2

No. of add'l. copies @ 30¢ per page

 \Box

MAY 15 ZUU6